


Parts needed to assemble and mount the W2 fastener set




Tools needed for mounting:

- Allen wrench
- drill
- pliers

NOTE! A list of products corresponding with the selected accessories is available at www.klusdesign.eu/uk.






www.klusdesign.eu/uk




7. Drill a hole with a diameter of 5 mm in the selected extrusion.







9. Mount the plastic bolt (B), on the top put the plastic base (C) and conductive head (D).



 ${f 10}$. Run the cable (A) through the hole in the plastic bolt and connect power to the LED strip.



 ${\bf 11}$. Insert the arm (E) into the mounting bracket of the head. It must press the power cable. Block the arm by tightening the pressure screw in the head with the Allen wrench.



12. Attach the light fixture with the arm (E) to the top head (F). Block the arm by tightening the pressure screw in the top head with the Allen wrench.

