


Parts needed to assemble the HR-LINE extrusion.



Tools needed for mounting:


- drill
- mounting adhesive
- silicone


NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure. More mounting procedures and related accessories can be found at klusdesign.eu

Turn off LED lights during peak day light hours in outdoor applications to avoid excessive heat buildup which will result in diminished LED life.







KLUŚ Inspiring Solutions