KLUŚ ® | Inspiring Solutions

Parts needed to mount the POLI extrusion

Extrusion (A)

End cap (B)

Cover (C)

LED strip (D)

Mounting bracket (E)

Tools needed for mounting:

- mounting glue

NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.
More mounting procedures and related accessories can be found at www.klusdesign.eu

1. Attach the mounting bracket (E) to the surface using the appropriate glue.

E

2. Mount the LED strip (D), insert the cover (C), and then insert the end cap (B).

A

D

B

C

3. Insert the extrusion (A) into the mounting bracket (E).

E