


**Parts needed to mount the DP-MOC fastener**



**Tools needed for mounting:**


- Allen wrench

**NOTE!** A list of products corresponding with the selected accessories is available at [www.KlusDesign.eu](http://www.KlusDesign.eu)

**1.** Insert an assembled lighting fixture in the mounting bracket of the head (A).



**2.** Insert the rod in the head (B). Block the rod by tightening the pressure screw in the head with the Allen wrench.



**3.** Suspend the lighting fixture using a selected system.

