


Parts needed to mount the DP-MOC-ZZ fastener




Tools needed for mounting:


- drill
- pliers
- Allen wrench
- soldering tool

NOTE! A list of products corresponding with the selected accessories is available at www.KlusDesign.eu

1. Insert an assembled lighting fixture into the mounting bracket of the head (A) and connect one pole of the cable to the power connector (C).



2. Insert the rod into the mounting bracket of the head (D). Block the rod by tightening the pressure screw in the head with the Allen wrench.



3. Suspend the lighting fixture using a selected suspension and power supply system

