

Parts needed to mount the 45-16 extrusion



Mounting bracket (A)



Extrusion (B)



LED strip (C)



Cover (D)



End Cap (E)


Tools needed for mounting:

- drill
- screwdriver
- screws


NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.
More mounting procedures and related accessories can be found at www.klusdesign.eu

1. Feed the power cable. Attach the mounting bracket (A) to the mounting surface with screws.



2. Mount the LED strip (C) in the extrusion (B) and insert the cover (D).



3. Connect power to the LED strip and mount the extrusion in the mounting bracket. Insert the end cap.

