

## Parts needed to mount the MICRO-K extrusion



## **Tools needed for mounting:**

- mounting glue

**WARNING!** All LED strips should be connected to a 12 V or 24 V power supply.


**IMPORTANT:** The mounting instructions present the basic form of assembly. More methods and related accessories can be found at www.KlusDesign.eu


www.KlusDesign.eu 1




 $\boldsymbol{1}_{\bullet}$  Install the LED strip (B) in the extrusion (A), insert the cover (C) and the end caps (D).

 $\mathbf{2}_{ullet}$  Feed the power cable. Spread the glue inside the mounting channel





 ${f 3}$  . Connect power to the LED strip and mount the extrusion (A) in the mounting channel.



A

www.KlusDesign.eu 2