


Parts needed to mount the MULTI-A extrusion



Tools needed for mounting:

- drill
- screwdriver
- screws
- Allen wrench

WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly. More methods and related accessories can be found at www.KlusDesign.eu

www.KlusDesign.eu 1






 $\mathbf{2}_{ullet}$ Mount the LED strips (F) and insert the power cable into the channel in the 1. Drill holes in the extrusion (A) for bolts and for the power cable. midsection of the extrusion (A). $oldsymbol{4}_{ullet}$ Insert the cover (D) and the end caps (C). ${\bf 3}_{\bullet}$ Mount the extrusion (A) to the mounting surface with screws and connect the power cable. D C


www.KlusDesign.eu 2




1.6 Drill holes in the mounting strip (B) and in the extrusion (A) to lead the power cable out. The hole in the mounting strip (B) should be in the middle of its length.





2. Mount the LED strips (F) and feed the power cable into the channel in the middle part of the extrusion (A) and through the hole in the mounting strip (B). Assemble the extrusion with the mounting strip.




3. Connect the power cables to the fasteners (E). One pole must be connected to one fastener. Download the <u>fastener manual</u> at KlusDesign.eu











5. Insert the cover (D) and the end caps (C).







www.KlusDesign.eu 3