


Tools needed when mounting:


- drill

NOTE! A list of products corresponding with the selected accessories is available at www.klusdesign.eu/uk.


1. Drill a hole in the concrete wall 10mm in diameter.



2. Insert the M5 mounting set into the drilled hole.



3. Insert the selected fixture/ extrusion into the mounting bracket.



4. ATTENTION! POSITION OF THE FIXTURE CAN BE REGULATED on the arm in a range of 300 degrees.300°.

